

Daily UpdateApril 22 and 23

Geological Work

Devil's Slide (post mile 39.14)

Work to clear the lower cliff and road of rocks and debris proceeded as planned. A rock catchment ditch was constructed above the road as a precaution against any future rock falls. Drilling operations are due to resume Monday April 24.

Repair Work

Slide at Post Mile 40

 Excavation work was completed by removing soil to a point below the slide plane. Staring Monday April 24, repairs will begin by installing drains. Rocks will be placed to back fill along with layers of soil and a reinforcing fabric that 'ties' the whole mass together.

Traffic Operations

• Channelizers, installed Friday April 21 on Highways 1 and 92, were inspected to verify compliance with the design. At the time of inspection, traffic was moving smoothly through the areas.